

Type Earth	Repair_Nee No	Inspection 10/19/2018	Comment 	Max_PDOP 3.0	Max_HDOP 2.1	Corr_Type Postprocessed Code	Rcvr_Type Geo 7X (H-Star)	GPS_Date 10/19/2018	GPS_Time 09:22:39am	Update_Sta New	Feat_Name Outfalls	Datafile GREAT FLATS.cor	Unfit_Pos 25	Flit_Pos 25	GPS_Week 2023	GPS_Second 483776.000	Latitude 42.814152080	Longitude -73.982001366			
Type Prefab	Stucture_c Good	Repair_nee 	Grate_cond Good	Repair_ne2 	Inspection 43392.0	Comment 	Max_PDOP 	Max_HDOP 3	Corr_Type 1.7 L1L2 Postprocessed Carrier Float	Rcvr_Type Geo 7X (H-Star)	GPS_Date 	GPS_Time 43392 09:21:47am	Update_Sta New	Feat_Name Catch_ba	Datafile GREAT FLATS.cor	Unfit_Pos 24.000	Flit_Pos 	GPS_Week 24 2023	GPS_Second 483724	Latitude 42.81396298	Longitude -73.98194926