

Fencing	Overgrowth	Debris	Dig_Out	Inspection	Max_PDOP	Max_HDOP	Corr_Type	Rcvr_Type	GPS_Date	GPS_Time	Update_Sta	Feat_Name	Datafile	Unfilt_Pos	Filt_Pos	GPS_Wr	GPS_Second	Latitude	Longitude
Good	Clear	No	No	4/19/2018	3.3	1.8	L1L2 Postprocessed Carrier Float	Geo 7X (H-Star)	4/19/2018	08:29:23am	New	Retentio	PONDS 4 19 18.cor	45	45	1997	394180.000	42.763241852	-73.926729587
Good	Clear	No	No	4/19/2018	4.2	2.5	L1L2 Postprocessed Carrier Float	Geo 7X (H-Star)	4/19/2018	08:56:57am	New	Retentio	PONDS 4 19 18.cor	28	28	1997	395834.000	42.771772363	-73.946005413
Good	Clear	No	No	4/19/2018	3.2	2.1	Postprocessed Code	Geo 7X (H-Star)	4/19/2018	09:07:01am	New	Retentio	PONDS 4 19 18.cor	39	39	1997	396438.000	42.771749886	-73.961878222
Good	Clear	No	No	4/19/2018	4.7	3.8	Postprocessed Code	Geo 7X (H-Star)	4/19/2018	09:54:44am	New	Retentio	PONDS 4 19 18.cor	30	30	1997	399301.000	42.762321823	-74.003327220
				4/19/2018	2.8	1.7	L1L2 Postprocessed Carrier Float	Geo 7X (H-Star)	4/19/2018	10:09:38am	New	Retentio	PONDS 4 19 18.cor	22	22	1997	400195.000	42.776929114	-74.007491970
Good	Clear	No	No	4/19/2018	2.6	1.3	L1L2 Postprocessed Carrier Float	Geo 7X (H-Star)	4/19/2018	10:20:14am	New	Retentio	PONDS 4 19 18.cor	23	23	1997	400831.000	42.779887888	-74.006377435
Good	Needs Cleaning	No	No	4/19/2018	2.4	1.4	Postprocessed Code	Geo 7X (H-Star)	4/19/2018	11:42:00am	New	Retentio	PONDS 4 19 18.cor	43	43	1997	405737.000	42.790917154	-74.003798969
Needs Repair	Needs Cleaning	No	No	4/19/2018	2.3	1.2	Postprocessed Code	Geo 7X (H-Star)	4/19/2018	01:30:07pm	New	Retentio	PONDS 4 19 18.cor	23	23	1997	412224.000	42.775475481	-74.009661255
Good	Clear	No	No	4/23/2018	1.7	0.8	L1L2 Postprocessed Carrier Float	Geo 7X (H-Star)	4/23/2018	11:44:12am	New	Retentio	PONDS 4 23 18.cor	21	21	1998	146669.000	42.763123709	-73.971450280
Good	Clear	No	No	4/23/2018	4.0	2.5	Postprocessed Code	Geo 7X (H-Star)	4/23/2018	11:53:49am	New	Retentio	PONDS 4 23 18.cor	25	25	1998	147246.000	42.763629203	-73.978056913